

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-018118**Date Inspected:** 07-Nov-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC) Chanxing Island**Location:** Shanghai, China**CWI Name:** Mr. Xu Tao**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Bike Path**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance Inspector (QA), Vibin Kumar Selvanayaham, was present during the times noted above for observations relative to the work being performed.

Magnetic Particle Testing (MT) – NWIT Document No's: 007266

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The members are identified as OBG Bike Path. The weld designations reviewed are as follows:

1. BK006A6-002-001, 002, 007, 165
2. BK006A8-002-001, 002, 007, 130

Bay 19

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW) welding of weld joint SB021-096-007 located on Suspender Bracket SB096E. ZPMC Welder is identified as 058772. ZPMC Quality Control (QC) is identified as Mr. Xu Tao. The welding variables recorded by QC appeared to comply with the Applicable WPS -B-T-2231-Tc-U4b-F.

FCAW welding of weld joint SB018-096-025 and 031 located on Suspender Bracket SB90W. ZPMC Welder is

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

identified as 062783. ZPMC Quality Control (QC) is identified as Mr. Xu Tao. The welding variables recorded by QC appeared to comply with the Applicable WPS -B-T-2233-Tc-U4b-F.

FCAW welding of weld joint SB018-100-006 and 072 located on Suspender Bracket SB100W. ZPMC Welder is identified as 062807. ZPMC Quality Control (QC) is identified as Mr. Xu Tao. The welding variables recorded by QC appeared to comply with the Applicable WPS -B-T-2132.



This QA inspector observed ABF personnel performed Magnetic Particle Testing on bottom cover plate of OBG Bike Path BK004A-009.

This QA inspector observed ABF personnel performed Magnetic Particle Testing on bottom cover plate of OBG Bike Path BK004A-010 and BK004A-001.

This QA inspector observed ABF personnel performed Ultrasonic Testing on OBG Suspender Bracket SB104E, SB104W, SB106E and SB106W.

FCAW welding of weld joint BK004A1-001-014, 015, 028 and 029 located on Bike Path. ZPMC Welder is identified as 062786. ZPMC Quality Control (QC) is identified as Mr. Guo Xing Hui. The welding variables recorded by QC appeared to comply with the Applicable WPS -B-T-2132.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.



Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact , who represents the Office of Structural Materials for your project.

Inspected By: Kumar,Vibin

Quality Assurance Inspector

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Reviewed By: Patel,Hiranch

QA Reviewer